


□ Ferrite Bead FB43-1801
 All wire 22AWG.

⚠ Connect Blue wire to clamp for positive biased gases, except HCHD & HZ. For HZ & HCHD connect to Block #JF2S. Connect blue wire to Banana Plug for negative biased gases. Connect White/Red wire to Banana Plug for positive biased gases, and to clamp for negative biased.

 Interscan Corporation 2700 Nordhoff St. Chatsworth, CA 91311		TITLE:	
Revisions:		4000 Series UL Wiring Diagram	
DATE:	09/22/98	TOL:	
Drawn By:	GM	Checked:	GM
Approved:		SCALE:	DRAWING NO.: